

## Personal Information

**Name:** GoodCarChoice, Earl  
**Address:** 25731 valley Park Terr.  
 Damascus Md, 20872  
**Phone:** 555-555-5555  
**Email Address:** egoodcarchoice@nolemons.com

The On-Site  
 Auto Inspection  
 &  
 Appraisal  
 Service

**Auto  
 Analyst**



## Vehicle Information

**Vehicle:** 2014 Hyundai Sonata Turbo    **Vin#:** 5NPEC4AB6EH899350    **Mileage:** 8472    **Technician:** Jeff    **Date:** 2015-12-17

## Exterior Condition

*Numerical Ratings: 1= New/Excellent 2= Good/Minimal wear 3= Satisfactory/Normal wear 4= Poor/Needs repair*

<b>Fender (Left):</b>	2: Good	<b>Front Bumper/Nose:</b>	2: Good
<b>Doors (Left):</b>	2: Good	<b>Grill Assembly:</b>	2: Good
<b>Quarter Panel (Left):</b>	2: Good	<b>Rear Bumper/Valence:</b>	2: Good
<b>Fender (Right):</b>	3: Repainted	<b>Chrome/Moldings:</b>	2: Good
<b>Doors (Right):</b>	2: Good	<b>Glass:</b>	2: Good
<b>Quarter Panel (Right):</b>	2: Good	<b>Lenses/Headlamps:</b>	2: Good
<b>Hood/Bonnet:</b>	2: Good	<b>Antenna:</b>	2: Good
<b>Roof/Convertible Top:</b>	2: Good	<b>Wiper Blades:</b>	2: Good
<b>Trunk/Deck Lid:</b>	2: Good	<b>Paint/Finish:</b>	2: Good - Some repaint
<b>Exterior Comments</b>	Right front fender repainted. The panel is original. May not be the result of an accident. No sign of frame repairs/damage. Average to good condition overall.		

## Interior Condition

*Numerical Ratings: 1= New/Excellent 2= Good/Minimal wear 3= Satisfactory/Normal wear 4= Poor/Needs repair*

<b>Front Seats:</b>	2: Good - Minimal wear	<b>Passenger Door Panels:</b>	2: Good - Minimal wear
<b>Back Seats:</b>	2: Good - Minimal wear	<b>Dashboard:</b>	2: Good - Minimal wear
<b>Headliner:</b>	2: Good - Minimal wear	<b>Console:</b>	2: Good - Minimal wear
<b>Sun Visors:</b>	2: Good - Minimal wear	<b>Spare Tire:</b>	1: New - Never used
<b>Carpet:</b>	2: Good - Minimal wear	<b>Jack/Lug Wrench:</b>	1: New - Never used
<b>Drivers Door Panels:</b>	2: Good - Minimal wear		
<b>Interior Comments</b>	Good condition overall.		

## Engine and Systems

Numerical Ratings: 1= New/Excellent 2= Good/Minimal wear 3= Satisfactory/Normal wear 4= Poor/Needs repair

<b>Oil:</b>	4: Dirty - Change now	<b>A/C Compressor:</b>	2: Good - No leaks
<b>Transmission Fluid:</b>	Not applicable - Sealed transmission	<b>Brake Cylinders:</b>	2: Good - No leaks
<b>Brake Fluid:</b>	1: Fresh - Recently changed	<b>Air Filter:</b>	2: Clean
<b>Power Steering Fluid:</b>	1: Fresh - Recently changed	<b>Valve Cover Gaskets:</b>	2: Good - No leaks
<b>Coolant Protection:</b>	1: Fresh - Recently flushed	<b>Oil Pan Gasket:</b>	2: Good - No leaks
<b>Washer Fluid:</b>	1: Fresh - Recently filled	<b>Other Seals/Gaskets:</b>	2: Good - No leaks
<b>Water Pump Belt:</b>	2: Good - No cracking or glazing	<b>Sending Switches:</b>	2: Good - No leaks
<b>Alternator Belt:</b>	2: Good - No cracking or glazing	<b>Exhaust Manifold:</b>	2: Good - No leaks
<b>Power Steering Belt:</b>	2: Good - No cracking or glazing	<b>Motor/Trans Mounts:</b>	2: Good - Original, minimal wear
<b>A/C Belt:</b>	2: Good - No cracking or glazing	<b>Electrical Wiring:</b>	2: Good - Original
<b>Coolant Hoses:</b>	2: Good - No cracking or bulging	<b>Battery Cables:</b>	2: Good - Original
<b>Power Steering Hoses:</b>	2: Good - No cracking or bulging	<b>Throttle Cable:</b>	2: Good - Original
<b>A/C Hoses:</b>	2: Good - Original - Minimal wear	<b>Clutch Cable:</b>	Not applicable
<b>Fuel Lines:</b>	2: Good - Original - Minimal wear	<b>Timing Belt:</b>	Not Applicable
<b>Hydraulic Lines:</b>	2: Good - Original - Minimal wear	<b>Plugs &amp; Ignition Wires:</b>	2: Good - Vehicle in tune
<b>Vacuum Lines:</b>	2: Good - Original - Minimal wear	<b>Alternator Voltage Output:</b>	14.75
<b>Trans Cooler/Lines:</b>	2: Good - Original - Minimal wear	<b>Alternator Comment:</b>	2: Good charging - Normal operation
<b>Oil Cooler/Lines:</b>	2: Good - Original - Minimal wear	<b>Battery Output:</b>	450CCA - OK
<b>Radiator:</b>	2: Good - No leaks	<b>A/C Output Temperature:</b>	60
<b>Water Pump:</b>	2: Good - No leaks	<b>A/C Comment:</b>	2: Good - Normal A/C operation
<b>Power Steering Pump:</b>	2: Good - No leaks		
<b>Engine &amp; Systems Comments</b>		Needs an oil change. All else good.	

## Undercarriage

Numerical Ratings: 1= New/Excellent 2= Good/Minimal wear 3= Satisfactory/Normal wear 4= Hazardous/Needs repair

<b>Differential (Leaks):</b>	Not applicable	<b>Front Springs/Shocks/Struts:</b>	2: Good - Little wear
<b>Transmission (Leaks):</b>	2: Good - No leaks	<b>Front Swaybars/Bushings:</b>	2: Good - No play
<b>Transfer Case (4wd):</b>	Not applicable	<b>Front Wheel Bearings:</b>	2: Good - No play
<b>Drive Shaft/U-Joints:</b>	Not applicable	<b>Tie Rods/Ends:</b>	2: Good - No play
<b>CV Joints/Boots:</b>	2: Good - No cracking and/or tears	<b>Ball Joints:</b>	2: Good - No play
<b>Fuel Tank:</b>	2: Good - No leaks	<b>Steering Box/Rack:</b>	2: Good - No leaks
<b>Exhaust System:</b>	2: Good - No leaks	<b>Front Wheels:</b>	2: Very clean
<b>Front Rotors:</b>	2: Good - No scoring and/or glazing	<b>Front Tires:</b>	2: Good - %75 tread remains
<b>Front Calipers:</b>	2: Good	<b>Rear Springs/Shocks:</b>	2: Good - Little wear
<b>Front Pads:</b>	2: Good - %75 pads remain	<b>Rear Swaybars/Bushings:</b>	2: Good - No play
<b>Front Lines/Hoses:</b>	2: Good - No cracking and/or leaks	<b>Rear Wheel Bearings:</b>	2: Good - No play
<b>Rear Rotors:</b>	2: Good - No scoring and/or glazing	<b>Rear Wheels:</b>	2: Very clean
<b>Rear Calipers:</b>	2: Good	<b>Rear Tires:</b>	2: Good - %75 tread remains
<b>Rear Pads:</b>	2: Good - %75 pads remain		
<b>Rear Line/Hoses:</b>	2: Good - No cracking and/or leaks		
<b>Undercarriage Comments</b>		Needs nothing now.	

## Accessories & Electronics Checklist

<b>Headlamps:</b>	Normal operation	<b>Seat Belts:</b>	Normal operation
<b>Tail Lights:</b>	Normal operation	<b>Warning Lights:</b>	Normal operation
<b>Brake Lights:</b>	Normal operation	<b>Horn:</b>	Normal operation
<b>Turn Signals:</b>	Normal operation	<b>Fan Switch:</b>	Normal operation
<b>Reverse Lights:</b>	Normal operation	<b>Cigarette Lighter:</b>	Not applicable
<b>Tag Lights:</b>	Normal operation	<b>Shifter/Neutral Safety Switch:</b>	Normal operation
<b>A/C &amp; Heater Controls:</b>	Normal operation	<b>Seat Adjustments:</b>	Normal operation
<b>Parking Lights:</b>	Normal operation	<b>Door Locks:</b>	Normal operation
<b>Marker Lights:</b>	Normal operation	<b>Windows:</b>	Normal operation
<b>Hazard Flashers:</b>	Normal operation	<b>Mirrors:</b>	Normal operation
<b>Interior &amp; Instrument Lights:</b>	Normal operation	<b>Radio/Tape/CD Player:</b>	Normal operation
<b>Wipers:</b>	Normal operation	<b>Navigation System:</b>	Normal operation
<b>Windshield Washers:</b>	Normal operation	<b>Cruise Control:</b>	Normal operation
<b>Sunroof:</b>	Normal operation	<b>Air Bags:</b>	Normal operation
<b>Emergency Brake:</b>	Normal operation	<b>Heated Seats:</b>	Normal operation
<b>Instrument Cluster/Gauges:</b>	Normal operation		
<b>Accessories &amp; Electronics Comments</b>			All working.

## Test Drive

<b>Engine Operation:</b>	Smooth idle - All systems normal
<b>Transmission &amp; Clutch:</b>	Good shift points in all gears
<b>Handling &amp; Steering:</b>	Good - No play or shimmy
<b>Braking:</b>	Good - No fade or pull
<b>Four Wheel Drive:</b>	Not applicable

## Technician's Appraisal

<b>NADA Retail: \$</b>	<b>22325.00</b>	<b>Market Area Wholesale: \$</b>	<b>17800.00</b>	<b>Auto Analyst Appraised Value: \$</b>	<b>21000.00</b>
------------------------	-----------------	----------------------------------	-----------------	---	-----------------

<b>Report Summary:</b>	Average to good condition overall. Needs an oil change.
------------------------	---

## Waiver & Limitation of Liability

*Auto Analyst, and the individual inspector, have performed a visual inspection of the subject automobile, and have analyzed various functional aspects of the noted component systems. No warranties, express or implied, are given as to the value of the automobile inspected, and no conclusions are offered as to the function of component parts other than the physical conditions revealed by the inspection and analysis. The written inspection report shall constitute the entire representation made by Auto Analyst, and the company shall have no liability upon any oral representations. The customer agrees that in no event shall the liability of Auto Analyst, or the inspector exceed the cost of this report whether claim is based on service contract, or for personal injuries.*

**Amount due: \$ 169.00**

Payment is due upon receipt. Thank you for your patronage.