

Personal Information

Name: LemonAvoider, Bob
Address: 2001 Bedford La
 Alexandria Va, 22307
Phone: 555-555-5555
Email Address: blemonavoider@nolemons.com



Vehicle Information

Vehicle: 2005 Lexus SC430 **Vin#:** JTHFN48Y850071322 **Mileage:** 65497 **Technician:** Jeff **Date:** 2015-11-07

Exterior Condition

Numerical Ratings: 1= New/Excellent 2= Good/Minimal wear 3= Satisfactory/Normal wear 4= Poor/Needs repair

Fender (Left):	3: Damaged - Replaced	Front Bumper/Nose:	3: Damaged - Replaced
Doors (Left):	3: Damaged - Repaired	Grill Assembly:	2: Good
Quarter Panel (Left):	3: Damaged - Repaired	Rear Bumper/Valence:	3: OK - Normal aging
Fender (Right):	3: Damaged - Replaced	Chrome/Moldings:	3: OK - Normal wear
Doors (Right):	3: Damaged - Repaired	Glass:	2: Good
Quarter Panel (Right):	3: Damaged - Repaired	Lenses/Headlamps:	2: Good
Hood/Bonnet:	3: Damaged - Replaced	Antenna:	2: Good
Roof/Convertible Top:	3: Damaged - Repaired	Wiper Blades:	2: Good
Trunk/Deck Lid:	3: Damaged - Repaired	Paint/Finish:	3: OK - All repainted
Exterior Comments	Car had major front end collision. Both fenders, hood, bumper valence and impact bar replaced. Grill and windshield also replaced. Likely air bag deployment. Rest of car is repainted. There is some body work on drivers door and left quarter panel. Frame damage evident. Fair to average condition overall. Trunk lid needs shocks.		

Interior Condition

Numerical Ratings: 1= New/Excellent 2= Good/Minimal wear 3= Satisfactory/Normal wear 4= Poor/Needs repair

Front Seats:	3: OK - Minor stains	Passenger Door Panels:	3: OK - Normal wear
Back Seats:	3: OK - Normal wear	Dashboard:	3: OK - Normal wear
Headliner:	3: OK - Normal wear	Console:	3: OK - Normal wear
Sun Visors:	3: OK - Normal wear	Spare Tire:	2: Good
Carpet:	3: OK - Minor stains - Needs cleaning	Jack/Lug Wrench:	2: Good
Drivers Door Panels:	3: OK - Normal wear		
Interior Comments	Some excess wear. Some staining. Hole in carpet by drivers seat. Fair to average overall.		

Engine and Systems

Numerical Ratings: 1= New/Excellent 2= Good/Minimal wear 3= Satisfactory/Normal wear 4= Poor/Needs repair

Oil:	2: Good - Clean and full	A/C Compressor:	3: OK - No leaks, normal wear
Transmission Fluid:	Not applicable - Sealed transmission	Brake Cylinders:	2: Good - No leaks
Brake Fluid:	2: Good - Clean and full	Air Filter:	1: New - Replaced recently
Power Steering Fluid:	3: OK - Change soon	Valve Cover Gaskets:	3: OK - Normal wear, no leaks
Coolant Protection:	2: Good - -40 Clean and full	Oil Pan Gasket:	3: OK - Normal wear, no leaks
Washer Fluid:	2: Good - Plenty of fluid	Other Seals/Gaskets:	3: OK - Normal wear, no leaks
Water Pump Belt:	2: Good - No cracking or glazing	Sending Switches:	3: OK - Normal wear, no leaks
Alternator Belt:	2: Good - No cracking or glazing	Exhaust Manifold:	3: OK - Normal wear, no leaks
Power Steering Belt:	2: Good - No cracking or glazing	Motor/Trans Mounts:	3: OK - Original, normal wear
A/C Belt:	2: Good - No cracking or glazing	Electrical Wiring:	3: OK - Original
Coolant Hoses:	2: Good - No cracking or bulging	Battery Cables:	3: OK - Original
Power Steering Hoses:	3: OK - Original - Normal wear	Throttle Cable:	3: OK - Original
A/C Hoses:	3: OK - Original - Normal wear	Clutch Cable:	Not applicable
Fuel Lines:	3: OK - Original - Normal wear	Timing Belt:	Not Applicable
Hydraulic Lines:	3: OK - Original - Normal wear	Plugs & Ignition Wires:	3: OK - Vehicle in tune
Vacuum Lines:	3: OK - Original - Normal wear	Alternator Voltage Output:	14.41
Trans Cooler/Lines:	Not applicable	Alternater Comment:	2: Good charging - Normal operation
Oil Cooler/Lines:	Not applicable	Battery Output:	555CA - OK
Radiator:	2: Good - No leaks	A/C Output Temperature:	55
Water Pump:	3: OK - No leaks, normal wear	A/C Comment:	2: Good - Normal A/C operation
Power Steering Pump:	3: OK - No leaks, normal wear		
Engine & Systems Comments	Has a squeaky belt tensioner. Will need power steering flush soon. No engine codes. All else OK.		

Undercarriage

Numerical Ratings: 1= New/Excellent 2= Good/Minimal wear 3= Satisfactory/Normal wear 4= Hazardous/Needs repair

Differential (Leaks):	2: Good - No leaks	Front Springs/Shocks/Struts:	3: OK - Normal wear
Transmission (Leaks):	3: OK	Front Swaybars/Bushings:	3: OK - Normal wear
Transfer Case (4wd):	Not applicable	Front Wheel Bearings:	3: OK - Normal wear
Drive Shaft/U-Joints:	3: OK	Tie Rods/Ends:	3: OK - Normal wear
CV Joints/Boots:	2: Good - No cracking and/or tears	Ball Joints:	3: OK - Normal wear
Fuel Tank:	3: OK - No leaks	Steering Box/Rack:	3: OK - Normal wear
Exhaust System:	3: OK - Normal surface rust	Front Wheels:	3: OK - Curb rash
Front Rotors:	2: Good - No scoring and/or glazing	Front Tires:	3: OK - %50 tread remains
Front Calipers:	2: Good	Rear Springs/Shocks:	3: OK - Normal wear
Front Pads:	2: Good - %75 pads remain	Rear Swaybars/Bushings:	3: OK - Normal wear
Front Lines/Hoses:	2: Good - No cracking and/or leaks	Rear Wheel Bearings:	3: OK - Normal wear
Rear Rotors:	2: Good - No scoring and/or glazing	Rear Wheels:	3: OK - Curb rash
Rear Calipers:	2: Good	Rear Tires:	3: OK - %50 tread remains
Rear Pads:	3: OK - %50 pads remain		
Rear Line/Hoses:	2: Good - No cracking and/or leaks		
Undercarriage Comments	Bad curb rash on all wheels.left lower ball joint is worn - replace soon. Frame has been pulled. All else OK.		

Accessories & Electronics Checklist

Headlamps:	Normal operation	Seat Belts:	Normal operation
Tail Lights:	Normal operation	Warning Lights:	Normal operation
Brake Lights:	Normal operation	Horn:	Normal operation
Turn Signals:	Normal operation	Fan Switch:	Normal operation
Reverse Lights:	Normal operation	Cigarette Lighter:	Inoperable/broken
Tag Lights:	Normal operation	Shifter/Neutral Safety Switch:	Normal operation
A/C & Heater Controls:	Normal operation	Seat Adjustments:	Normal operation
Parking Lights:	Normal operation	Door Locks:	Normal operation
Marker Lights:	Normal operation	Windows:	Normal operation
Hazard Flashers:	Normal operation	Mirrors:	Normal operation
Interior & Instrument Lights:	Normal operation	Radio/Tape/CD Player:	Normal operation
Wipers:	Normal operation	Navigation System:	Normal operation
Windshield Washers:	Normal operation	Cruise Control:	Normal operation
Sunroof:	Normal operation	Air Bags:	Normal operation
Emergency Brake:	Normal operation	Heated Seats:	Normal operation
Instrument Cluster/Gauges:	Normal operation		
Accessories & Electronics Comments		Lighter does not work - socket is OK. All else working.	

Test Drive

Engine Operation:	Smooth idle - All systems normal
Transmission & Clutch:	Good shift points in all gears
Handling & Steering:	Good - No play or shimmy
Braking:	Good - No fade or pull
Four Wheel Drive:	Not applicable

Technician's Appraisal

NADA Retail: \$	23175.00	Market Area Wholesale: \$	14500.00	Auto Analyst Appraised Value: \$	17800.00
------------------------	-----------------	----------------------------------	-----------------	---	-----------------

Report Summary:	Rough to Fair condition overall. Trunk lid needs shocks. Will need maintenance and repairs soon.
------------------------	--

Waiver & Limitation of Liability

Auto Analyst, and the individual inspector, have performed a visual inspection of the subject automobile, and have analyzed various functional aspects of the noted component systems. No warranties, express or implied, are given as to the value of the automobile inspected, and no conclusions are offered as to the function of component parts other than the physical conditions revealed by the inspection and analysis. The written inspection report shall constitute the entire representation made by Auto Analyst, and the company shall have no liability upon any oral representations. The customer agrees that in no event shall the liability of Auto Analyst, or the inspector exceed the cost of this report whether claim is based on service contract, or for personal injuries.

Amount due: \$ 159.00

Payment is due upon receipt. Thank you for your patronage.